

Oil Field Environmental Incident Summary

Incident: 20160829123515 **Date/Time of Notice:** 08/29/2016 12:35

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: SHELL 23-2820H

Field Name: PARSHALL

Well File #: 30781

Date Incident: 8/29/2016 **Time Incident:** 01:45

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 89

Sec: 28

Qtr:

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Person: Danielle Dupay
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	10	Barrels	9	Barrels	10	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/4/2017

Clean Up Concluded: 9/8/2016

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Operations was shut down and the valve was closed. The liquids were removed from the ground via vac truck and pumping resumed. When frac operations are complete and equipment removed from site the area affected will be re-assessed for further cleanup.

Wastes Disposal Location: Liquids SWD, Solids TBD

Agencies Involved:

Updates

Date: 8/29/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was contained to the well pad. NDIC retains oversight.